



## Specifications: Stick-M-Up-Ready-To-Use Available in 5 Gallon Pails Only

Appearance:	Clear purple liquid
Odor:	Mint
Boiling Point:	No data
Vapor Density:	No data
pH:	>11.5
Flash Point:	No data
DOT Shipping Class:	70
Shipping Weight:	5 gal. pail 46 lbs.
Specific Gravity:	~1.08
Solubility:	Complete in water
Stability:	Stable
Viscosity:	Thin
Coverage Rate:	150-200 sq. ft/gal over glue
% Volatile	No data
HMIS Rating:	1-1-0
DOT Shipping Name:	UN3266, PAINT RELATED MATERIAL, 8, PGII

**Twin-Chemicals  
Atlanta, Georgia**

**(800) 442-4958  
(770) 924-6147 fax**

**www.twinchemicals.com**



STICK-M-UP allows for quick removal of glued down carpet and acrylic, latex and pressure sensitive adhesives from concrete, terrazzo, ceramic tile and other surfaces. It is designed to soften carpet adhesive so that carpet may be easily removed and to allow for easy scrape removal of the carpet adhesive. STICK-M-UP is water based and is non-flammable. ***Does not contain: methylene chloride, benzene, toluene, phosphates, chlorinated solvents or petroleum distillates.***

Directions: Read and understand SDS when using this product.

#### **To Remove Adhesive From Substrate (where floor covering has already been removed)**

Spray, pour or mop solution onto the adhesive making sure to completely cover the area to be worked. The floor area should not be allowed to dry. Make sure that "high areas" in the working area are kept wet. Allow at least 20 minutes dwell time before beginning to work the areas. Use scrapers or propane strippers with Nylo-Grit brushes or similar equipment. Discard removed adhesive and then rinse the floor with clean water, mop and allow to dry.

#### **To Remove Glued Down Carpet**

Cut the carpet into workable sections approximately 2 feet wide, spray, pour or mop solution onto the carpet making sure to completely cover the area to be worked. Use a carpet roller or squeegee to help spread the solution evenly. Allow the solution to dwell for at least 1 hour. If possible allow the solution to work overnight. If leaving the solution over night, cover the work area with plastic sheeting to prevent excessive evaporation. Pull up carpet sections by hand and immediately begin scrapping away residual adhesive. Once the residual adhesive is removed, rinse and mop with clean water and allow to dry.

#### **To Remove Sheet Vinyl**

Cut the sheet vinyl into workable sections approximately 2 feet wide. Pull up wear layer. Spray, pour or mop solution onto the sheet vinyl backing making sure to completely cover the area to be worked. Allow the solution to dwell for at least one hour. Do not allow the floor area to dry. Remove backing and adhesive with scraper. Once the residual adhesive is removed, rinse and mop with clean water and allow to dry.

**WARRANTY NOTICE:** Seller makes no warranty, expressed or implied, nor accepts any responsibility for any direct or consequential damages beyond the purchase price, because seller cannot control users handling and use, or effect of use.